

MAYANGALORE MAHANAGARA PALIKE

INSPECTION REPORT

Division: Hebbal

Ward No. 18

Sub Division: Hebbal / JC Nagar

Descriptions

Details

Remarks

Name of the work

Construction of RCC drain and culverts in Jaladarshini Layout in Ward No. 18

Administrative Sanction No and Date

AC(E)AS/166-45/13-14 dated: 30/10/2013

Technical Sanction No and Date

EE(H)TS/90/13-14 dated: 30/10/2013

Job Number, date and P code

018-14-000001

Estimate Cost (Rs in Lakhs)

Rs. 15.00 Lakhs

Tender (or) Direct Entrustment to KRIDL

Tender

If tendered, Tender notification number date and publication in Daily news paper

EE/H/TEND/09/13-14 dated:

Tender Approval Details

Rs. 1416901.50

Date of work order and number

EE/H/AE/WO/186/13-14 dated: 23/08/2014

Stipulated time and completion

22/10/2014

Actual date of completion

30/09/2014

Delay if any

No Delay

Reasons for delay

Payment made till date

Payment due

Pending bill details status of work

Completed

Quality test report

Submitted

Photographs of the completed works

Submitted

M.B. No. and page number


770/11-12 P-76981-86

Bill form

Submitted

Remarks: Recommendations of the inspection team - Name / Mobile No / E-Mail

Certified that the above work is inspected on 09-03-2016, verified MB and bill file which are technically correct. Work is satisfactory. Bill payment may be released.

 9.3.16

G. R. Hiremath EE Retd.



G. R. Hiremath EE (Retd)
District Quality Monitor
Bruhat Bangalore Mahanagara Palike